



# RH40

## Station machining limit diagram

400 Max. cutting length

End face of spindle box

Chuck end face

Jaw end face

Maximum turning diameter

$\phi 400$

$\phi 85$

$\phi 120$

590 Max. workpiece length

